

KAIWEETS KC602 Clamp Meter Parameters

KC602	Parameters
DC Voltage	600mV/6V/60V/600V±(0.5%+5)
AC Voltage	600mV/6V/60V/600V±(0.8%+5)
DC Current	60A/600A±(2.5%+5)
AC Current	60A/600A50~60Hz: ±(2.5%+5) Other: ±(3.0%+10) INRUSH: ±(5.0%+10)
AC Inrush Current	60A/600A
Capacitance	6nF/60nF/600nF/6uF/ 60uF/600uF/6mF/60mF±(4.0%+5)
Resistance	600Ω/6kΩ/60kΩ/600kΩ/6MΩ/60MΩ±(1.0%+5)
Frequency	100Hz/1000Hz/10KHz/100KHz/1000KHz/10MHz±(1.0%+3)
Duty	1-99%
Certification	CE,EAC,FCC,RoHS
Display Type	Digital Only